

January 5, 2010 12:45:35 PM

Item ID: D3566-1

Accept

Setup Start



Stop

Stop

Revision ID:

Gasket Item Name:

Required Date: 15/01/2010

05/01/2010

QC:

Start Qty: 12,00 Reg'd Qty: \$.00

Cust Item ID:

Customer:

Reference:

Approvals:

Start Date:

Process Plan:

Date 10-1-05

Date:

Date:

Start Run



Sequence ID/ **Work Center ID** Operation Description Set Up/ **Run Hours**

SPC (Y/N):

Draw Number

Plan Draw Rev. Code

Accept Qty

Reject Qty

Number Stamp

Draw Nbr

Revision Nbr

D3566

Rev C

100

Waterjet

FLOW CNC Waterjet

FLOW WATER JET

Memo

0.00

0.00

1-Cut as per Dwg D3566 Dwg Rev: C DProg Rev: C 2-

R10-1-14

110

QC2- Inspect parts off machine FAI/FAIB

Deburr if necessary

0.00



Memo

0.00

1310-1-14

Quality Control

120

QC8- Inspect parts - second check

Memo

2) S wolvely

Quality Control

Dart Aerospace L	_td
------------------	-----

	WORK ORDER CHANGES							
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		1			i i			
	STEP					STEP PROCEDURE CHANGE By Date Qty Chief Eng /		

Part No: _	PAR	R #:	Fault Category:	NCR: Yes No	DQA:	Date:	
	Resolution:		Disposition:	QA: N/C Closed	•	Date:	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)						
D.4.T.F		Description of NC		Corrective Action Section B		Verification	n Approval Chief Eng		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Approval QC Inspector	
						:			

January 5, 2010 12:45:35 PM

Required Date: 15/01/2010

Item ID: **Revision ID:** D3566-1

Accept



Setup Start



Run

Item Name:

Start Date:

Gasket

05/01/2010

Start Qty: 12.00 Reg'd Qtys 12.00

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Rev.

Start

Stop



QC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop



Sequence ID/ **Work Center ID**

130

Packaging -

Packaging

Operation Description

Identify as per dwg & Stock Location:__

Memo

Memo

0.00

0.00

Draw

Number

Pian Code

Accept Qty

Reject Qty

Reject Number Stamp

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	GES		· · · · · · · · · · · · · · · · · · ·			
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							•			
Part No: PAR #:		Fault Categ	ory:	NCF	l: Yes	No DQ	A:	_ Date: _		
	R	esolution:	Disposition	N/C CI	osed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCR)			
DATE	OTED	Description of NC	Corrective Action		tion B	 า B		Verification A		Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		ion C	Approval Chief Eng	QC Inspector
				-	:					
:										
										:
ı	1	1	i i				- 1			1

Picklist Print

January 5, 2010 12:45:39 PM

Work Order ID: 55011

Parent Item:

D3566-1

Parent Item Name: Gasket

Comments:

Item Name

ID/	Repiacement	M ₂
	Item ID	Purca

MNEO60S.063

Component Item

Purchased

No



NEOPRENE SHEET 0.063



Start Date: 05/01/2010

Required Date: 15/01/2010

Page 1

Start Qty: 12.00

Required Qty: 12.00

Primary Location	Last Location	Route Seq ID	Unit of Measure	¥∜y on Mand	Remaining Qty To Pick	Qty Issued	Date Issued	Status

831.4955 11.5074

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
MAT	831.4955		
112508	61.6034		
112662	290.2821		
112866	154.11		
113058	325.5		113058)

sf

100

Dart Aerospace Ltd

	Copaco									
W/O:			WO	RK ORDER CHANG	GES					
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No: PAR #:		PAR #:	Fault Categ	ory:	NCR	: Yes	No DQ	A:	Date: _	
	Resolution:		Disposition	l:	QA:	N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	IANCE	(NCF	R)			
		Description of NC		Corrective Action Section			Vorifi	Verification	Approval Chief Eng	Approval QC Inspector
DATE	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		Sign 8 Date		ion C			
										<u>}</u>
										}

DART AEROSPACE LTD	Work Order:	55011
Description: Gasket	Part Number:	D3566-1
Inspection Dwg: D3566 Rev: C	· ·	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype


Drawing Dimension	,Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.10	+/-0.030	3,105	V			
18.00	+/-0.030	18.00	7			
12.10	+/-0.030	17.10	>			
2.43	+/-0.030	7.433	*			
6.00	+/-0.030	6.000	X			
1.40	+/-0.030	1.406	>			
0.30	+/-0.030	-306	8			
0.30	+/-0.030	303	8			
0.063	+/-0.010	,061	×			
Ø0.188	+0.005/-0.001	,188	a			
				,		
		_				
			,			
٠,						
,						

Measured by:	B	Audited by:	8	Prototype Approval:	N/A	
Date:	10-1-14	Date:	(0/0/14	Date:	N/A	

Rev	Date	Change	Revised by	Approved
Α	07.03.14	New Issue	KJ/JLM	
В	07.07.18	Dimensions updated per Dwg Rev. B	KJ/JLM LA	
С	07.09.26	Dwg Rev updated	KJ/EC/DD	C

Dart Ae	rospace Ltd								
W/O:			WORK ORDER	CHANGES					
DATE	STEP	PRO	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				:					
		en e							
Part No	:	PAR #:	Fault Category:	NCR: Yes	No DQ	A:	Date: _		
Resolution:		ı:	Disposition: QA		QA: N/C Closed:			Date:	
NCR:	WORK ORDER NON-CONFORMANCE (NCR)								
					 			T	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC	Corrective Action Section B			Verification		A		
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
						,				
V/A										



Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	ES	***			-
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		-							
		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date:	
		esolution:	Disposition:			QA: N/C Closed:			Date:
NCR:		\	WORK ORDE	ER NON-CONFORMA	NCE (NC	7)			
D.4	STEP	Description of NC Section A	Corrective Action S		on B	Verific	Verification	Approval	Approval
DATE			Initial Chief Eng	Action Description Chief Eng	Sign of Date	& Section	Section C	Chief Eng	QC Inspector
		1							